

The optimal printing range is 285 – 305°C

Up to 105°C with ABS slurry, or up to 140°C using a PVP-based glue stick.

-

- Automotive, aerospace, general manufacturing
- Housings (including battery housings)
- Welding fixtures

